



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas and Mining  
JOHN R. BAZA  
Division Director

### Minerals Inspection Report

Report Date: 08/26/2013

Reviewed *FB*

Mine Name: Maynard Topaz	Permit Number: S/023/0099	Mine Status: Active
Operator Name: : Colorado Calumet Co. Inc	Inspection Date: 08/22/2013	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time:	Bond Amount: \$4,000
Attendee(s):	Weather: 80's and clear skies	Bond Escalation: 08/04/2013
Inspection Purpose: Operator requested bond release		Prior Inspection: 08/10/2012

#### Conclusions and Recommendations


Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds The bond is for revegetation of three acres and should be adequate.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation The site was given Phase I bond release in 2011. The site is stable.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation In bond release application Operator stated that there was 0% premining vegetation and now 100% of the area was seeded. Images from Google Earth show that some of the disturbed area had vegetation prior to the Operator disturbing the site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: *Wayne Western*

CC: Lee Stokes, SITLA

File: /O/M023-Juab/S0230099-MaynardTopaz/inspections/Insp08222013.pdf






Google Earth 10/25/1997



Google Earth 09/24/2006



Google Earth 08/27/2009



Google Earth 10/02/2011





Reclaimed area looking west



Reclaimed area looking northwest



Bare area



Bare area





Looking north



Looking south

